



A REVOLUTION IN ARCHITECTURAL METAL

CARING FOR PEWTER SURFACES

Pewter surfaces are relatively easy to maintain, but yet they do come with some precautions. To properly care for pewter, adhere to the following:

Clean Regularly - Mild soap and water is all it takes to keep these surfaces clean. A basic daily or after-use wipe down is generally enough to maintain appearance and cleanliness.

Do Not Use Harsh Chemical Cleaners - This includes bleach products and other chemical abrasives. These cleaners are too harsh for the soft surface of pewter and can cause damage.

Do Not Use for Cutting - Pewter is softer than stainless steel. It resists scratches from general daily use, but the application of a sharp edge directly on the surface will leave an impression. We recommend the use of a cutting board.

Do Not Place Hot Items Directly on Surface - Pewter has a melting point of about 300 °F (approx. 150 °C). To avoid problems, use hotplates and trivets instead of placing hot pots and pans directly on surfaces.

Wax After Cleaning - To maintain the bright, shiny appearance of pewter, periodically apply a thin coat of beeswax after cleaning to protect the surface. Without this polishing, a natural patina will form in a few months' time.

224 E. BAY ST. SAVANNAH, GA 31401
866.570.9690 TEL 866.402.9690 FAX
WWW.BASTILLEMETALWORKS.COM